NPOL Sun calibration completed

styles/thumbnail/public/pictures/picture-39-1362775417.jpg?itok=63LpR-Cd Submitted by pdomaszc on Wed, 2013-05-08 11:39 Date:

Wednesday, May 8, 2013 - 11:30

Instrument List:

• Green

Discussion:

Sun calibration has been completed on NPOL this morning. We continue to run 10-min surveillance scans.

Beautiful weather in eastern lowa. Gearing up for possible precipitation in the IFloods domain later this evening.

PD